

From: [Roberts, Lou](#)
To: [Moore, Gary](#)
Subject: FW: Doyle Site - Leonard, Texas - TXD980865109 / Site ID #604997
Date: Thursday, August 10, 2017 4:54:29 PM

FYI

From: Roberts, Lou
Sent: Thursday, March 12, 2015 1:10 PM
To: Moore, Gary <moore.gary@epa.gov>
Subject: RE: Doyle Site - Leonard, Texas - TXD980865109 / Site ID #604997

Thanks Gary

Lou Roberts (6EN-HM)
US EPA Region 6
1445 Ross Avenue, Suite 1200
Dallas, TX 75202-2733
(214) 665-7579
Fax (214) 665-7446

"This email may contain material that is confidential, privileged and/or attorney work product and is for the sole use of the intended recipient. Any review, reliance or distribution by others or forwarding without express permission is strictly prohibited. If you are not the intended recipient, please contact the sender and delete all copies."

From: Moore, Gary
Sent: Thursday, March 12, 2015 12:12 PM
To: Roberts, Lou
Subject: FW: Doyle Site - Leonard, Texas - TXD980865109 / Site ID #604997

FYI

Gary Moore
Federal On-Scene Coordinator
U.S. EPA Region 6
214-789-1627 cell
214-665-6609 office
moore.gary@epa.gov

From: Sullivan, Robert
Sent: Monday, June 30, 2014 10:54 AM
To: Moore, Gary

Subject: RE: Doyle Site - Leonard, Texas - TXD980865109 / Site ID #604997

Gary.

I remember going there. It was an active site if I remember correctly and was referred to TCEQ. If I remember correctly EPA/TAT did sample?

Bob.

From: Moore, Gary

Sent: Friday, June 27, 2014 4:08 PM

To: Sullivan, Robert

Subject: FW: Doyle Site - Leonard, Texas - TXD980865109 / Site ID #604997

Bob:

They had your name by this in the lotus notes sites list. Do you know anything about this site? It is listed as Frank J. Doyle Site. See correspondence chain below:

Thanks

Gary Moore
Federal On-Scene Coordinator
U.S. EPA Region 6
214-789-1627 cell
214-665-6609 office
moore.gary@epa.gov

From: Ruhl, Christopher

Sent: Friday, June 27, 2014 2:14 PM

To: Sales, James

Cc: Webster, Susan; Moore, Gary

Subject: RE: Doyle Site - Leonard, Texas - TXD980865109 / Site ID #604997

James,

I am in receipt of your email. I am forwarding it to our folks that deal with PCB sites.

Chris Ruhl

USEPA R6 Oil Team Leader

Federal On Scene Coordinator

(214) 665-7356 office

From: Sales, James
Sent: Friday, June 27, 2014 1:55 PM
To: Ruhl, Christopher
Subject: FW: Doyle Site - Leonard, Texas - TXD980865109 / Site ID #604997

Hello—I talked to a consultant about this site yesterday. It was previously investigated by Region 6 Superfund, but no action was taken. The TCEQ is involved and contemplating enforcement action. The main issue for me is, PCBs have gone offsite into neighbors yards and what looks like a playground for children—I don't believe anyone has made an effort to warn the neighbors about allowing children to play in these areas or not growing vegetable gardens, not has any silt fence been put up at the property boundary to at least stop the offsite migrations of PCB contaminated soil I wondered if you could find who worked on this before, and if anything can be done by EPA Superfund on this site. Thanks

From: Rick Robertson [<mailto:rick@terra-solve.com>]
Sent: Monday, June 23, 2014 9:34 PM
To: Chris Zillmer; pindy.lall@tceq.texas.gov; Sales, James
Subject: RE: Doyle Site - Leonard, Texas - TXD980865109 / Site ID #604997

Gentlemen:

I just sent a link to Dropbox where I placed the EPA documents I received in 2010 in response to a FOIA request.

Pindy, I have some TCEQ documents that I would scan and include, too, but after several hours of trying, I have determined my scanner must be dead. If you can post your documents to Dropbox or send via email to all parties, that would be great. If not, I will have the hardcopies at the meeting.

Attached is a comprehensive Chronology of Events as I have determined them.

RICK ROBERTSON

CHARLES R. ROBERTSON, PG, CPG
TERRA-SOLVE, INC.
3216 COMMANDER DRIVE, SUITE 103
CARROLLTON, TX 75006

O 972.267.1900
F 972.267.1902
C 214.641.8155

WWW.TERRA-SOLVE.COM